



13 October 2009

**Atech Turbine Component Inc.**

1, St Mark Street  
Auburn, MA 01501 USA

**RE: Confirmation of the following Repair Development Approval:**

**Approval of the Facility for the Fuel Nozzle Sleeve Replacement on the Outer CC Liner of the PT6A-60 Series Models to the listed part numbers in the attached appendix.**

Dear Sirs:

This is to confirm that,

**Atech Turbine Component Inc.**  
Auburn, MA

have demonstrated to our satisfaction that they have the necessary knowledge, skills, facilities and controls to successfully perform **Fuel Nozzle Sleeve Replacement**, on the part numbers listed in appendix 1.

The demonstrated process is defined as **CL-1070H Rev: 00** dated **22 September 2009**, a copy of which has been deposited with Pratt & Whitney Canada Corp., Repair Development Engineering. This copy will be the document of reference in any dispute. Significant changes to, or deviations from, this process are not permitted without the written approval of the Pratt & Whitney Canada Repair Development Manager. Refer to appendix 2 for list of significant changes related to this process.

**Atech Turbine Component Inc.**

The intent of process **CL-1070H** will be reflected in the applicable engine Overhaul Manuals or CIR Manual as applicable. This letter is an authorization to proceed pending issue of the above revision. Use of this authorization is subject to compliance with local airworthiness authority requirements and all certificates issued for a given part repaired with the subject process must reflect the process number. Any subsequent part numbers introduced beyond those indicated in this letter require P&WC's specific approval.

Failure to maintain satisfactory controls and quality, to provide adequate service, or to adhere to the executed Repair Process Agreement, could result in loss of this approval and deletion of the supplier's name from the Overhaul Manuals or CIR Manual as applicable.

Revalidation of this approval will be required after two (2) years of inactivity.

Yours truly,

PRATT & WHITNEY CANADA CORP

This Letter has been electronically approved in accordance with the Customer Support Operating Procedure P3

Aline Miquet  
Manager  
Repair Development Engineering

Gerry Whitty  
Customer Support DAA  
DAA# 81 / DAO # 93-Q-01

C/C

J. Pelletier

Engine DAA

**REVISION HISTORY**

<b>Rev</b>	<b>Changes</b>
	-
<b>00</b>	Original issue dated <b>13 October 2009</b> , by Terry Shaw.

Atech Turbine Component Inc.

## Appendix 1

### List of applicable Part Numbers

3106006-01  
3106377-01  
3038148  
01R3038148  
02R3038148  
3055434-01  
3055435-01  
3055657-01  
3055663-01  
3070035-01  
3070268-01  
3112652-01  
3113294-01  
3115834-01  
01R3115834-01  
3115835-01  
01R3115835-01