

Pratt & Whitney Canada Corp.
1000, Marle-Victorin
Longueuil, Quebec, Canada J4G 1A1
450-677-9411



Pratt & Whitney Canada

Une société de United Technologies/A United Technologies Company

Letter 724002-AL-010

Rev: 00

5 June, 2002

Atech Turbine Inc
1, Saint Mark St
Auburn, MA
USA, 01501

RE: Confirmation of the following Repair Development Approval:

Approval of the Facility for the TDF modification on PT6A-60's models to the listed part numbers in the attached appendix.

Dear Sirs:

This is to confirm that,

Atech Turbine Inc
Auburn, MA
USA

Have demonstrated to our satisfaction that they have the necessary knowledge, skills, facilities and controls to successfully perform **TDF modification**, on the part numbers listed in appendix 1.

The demonstrated process is defined as **SB-1070 Rev: B** dated **12 Apr 2002**, a signed copy of which has been deposited with Pratt & Whitney Canada Corp., Repair and Overhaul Support. This copy will be the document of reference in any dispute and no changes to, nor deviations from, this process are permitted without the written approval of the Pratt & Whitney Canada Repair and Overhaul Support Manager.

The intent of process **SB-1070** will be reflected in the applicable engine Overhaul Manuals. This letter is an authorization to proceed pending issue of the above revision. Use of this authorization is subject to compliance with local airworthiness authority requirements. Any subsequent part numbers introduced beyond those indicated in this letter require P&WC's specific approval.

Letter 724002-AL-010
Rev: 00

Atech Turbine Inc

Failure to maintain satisfactory controls and quality, to provide adequate service, or to adhere to the executed Repair Process Agreement, could result in loss of this approval and deletion of the supplier's name from the Overhaul Manuals.

Revalidation of this approval will be required after two (2) years of inactivity.

Yours truly,

PRATT & WHITNEY CANADA CORP

This Letter has been electronically approved in accordance with the Customer Support Operating Procedure P3

Pierre Hurteau
Manager
Repair and Overhaul Support

Peter Boyd
Customer Support DAA
DAA# 13 / DAO # 93

C/C H. Pépin CRB
A. Goldman Engine DAA

Letter 724002-AL-010
Rev: 00

Atech Turbine Inc

Appendix 1
List of applicable Part Numbers

3106006-01	3106377-01	
------------	------------	--